




**AUTOMATED MERCHANDISING SYSTEMS
255 WEST BURR BLVD.
KEARNEYSVILLE, WV 25430
304-725-6921 e-mail service@amsvendors.com**


When updating the Insight firmware, you can only have one firmware on your USB stick



Turn your vendor off. Install the USB stick into the control board.



AUTOMATED MERCHANDISING SYSTEMS
255 WEST BURR BLVD.
KEARNEYSVILLE, WV 25430
304-725-6921 e-mail service@amsvendors.com



Light will flash when programming

Hold your blue service mode button down, turn the vendor on, the red light on the control board will start to flash, you can release the blue service mode button and wait for the red light to stop flashing.

Once the red light stops flashing, turn the vendor off, wait for about five seconds and then remove the USB stick, turn the vendor

Turn your vendor back on and, get into the service mode, press 7 to configure the motors, then proceed to reprogram your pricing, coupled motors or anything else special that was previous set.